

Fume Hood Report

as of 10/07/09

Date Entered	WO#	Work Order Description	Action Code	WO Status	Asset Number	LAST_NAME
7/1/2009	09-022129-000	POLYMER/CONTE ROOM B262. FUME HOOD WINDOW DOES NOT OPEN EASILY----PLEASE CHECK. □ REQ.EUNYOUNG@5-9685 RITB033978	Routine Service Call	Closed	BU0614-100	HUSTED
7/2/2009	09-022156-000	MORRILL 4 N, LAB 210, THE FUME HOOD IN LABORATORY 210 IN MORRILL FOUR NORTH IS NOT FUNCTIONING PROPERLY PLEASE INVESTIGATE FUME HOOD CONTROLS., □ REQ.MARC DUSZA , Phone: 5-4585 iNET	Routine Service Call	Closed	BU0347-100	HUSTED
7/2/2009	09-022188-000	MORRILL 4 NORTH 4TH FLOOR FUME HOODS ARE RUNNING AT 85%. PLEASE CHECK LOW FLOW. R-608@12:45PM □ REQ.JOY WARD@5-9469 RITB033994	Dispatch Service Call	Closed	BU0347-100	HUSTED
7/10/2009	09-023426-000	LEDERLE T/A 15TH FLOOR ROOM 1511. REPAIR FAULTY VALVE UNDER FUME HOOD.	Routine Service Call	Closed	BU0502-300	RENAUD
7/10/2009	09-023434-000	GOESSMANN LABORATORY, RM.226, FUME HOOD #0081-042/0081-039. TAGGED HOOD. LOW FLOW. □ REQ:DAMIEN NICODEMI@545 2682 iNET	Routine Service Call	Closed	FH0081-042	TOWNSEND
7/10/2009	09-023435-000	GOESSMANN LABORATORY, RM.226, FUME HOOD #0081-040/0081-041. TAGGED HOOD. HIGH FLOW. □ REQ:DAMIEN NICODEMI@545 2682 iNET	Routine Service Call	Closed	FH0081-040	TOWNSEND
7/13/2009	09-023878-000	GOESSMANN, 112 B, PLEASE CHECK ALL FUME HOODS IN THIS LAB FOR PROPER OPERATION. OCCUPANTS SUSPECT AT LEAST ONE DOES NOT WORK. THANKS, TS, □ REQ.TOM SPOONER, Phone: 5-2246 iNET	Routine Service Call	Closed	BU0081-100	HUSTED
7/13/2009	09-023886-000	NEW GOESSMANN LABORATORY, RM.166, FUME HOOD #FH0082-101 . TAGGED HOOD. HIGH FLOW. □ REQ:DAMIEN NICODEMI@545 2682 iNET	Routine Service Call	Ready	FH0082-101	TOWNSEND
7/14/2009	09-023918-000	LEDERLE GRADUATE CENTER A - RM 1509 , FH04121512, REPAIR DOOR, HARD TO OPEN AND CLOSE. FUME HOOD DOOR □ REQ. KEDAR 5-2642	Routine Service Call	Progressing	FH04121512	OCONNOR
7/17/2009	09-024717-000	CONTE FH0614-549 , 225, FUME HOOD HAS LOW FLOW. □ REQ.YUNG MORGAN, Phone: 545 2682 iNET	Routine Service Call	Closed	FH0614-549	LEE
7/28/2009	09-026816-000	LEDERLE, RM 125 FUME HOOD NOT STAYING IN CALIBRATION. REQ. RAY SAMSON @ 5-6416	Routine Service Call	Progressing	BU0412-110	SAMSON
7/29/2009	09-026883-000	GRC, FLOWTECH TO SUPPORT JIM WARREN WITH FUMEHOODS AND VSD DRIVES .REQ. RAY SAMSON @ 5-6416	Planned Work	Ready	BU0412-110	SAMSON
7/29/2009	09-026917-000	POLYMER RESEARCH CENTER, RM.642, FUMEHOODS 1-2 & 3, FLOW TOO LOW WHEN SASH 1/2 OPEN. □ REQ:KATRINA KRATZ@71632 RITB033770	Routine Service Call	Closed	BU0614-100	TOWNSEND
7/31/2009	09-027043-000	FERNALD HALL, CHECK FLOOR TILES IN ROOM 208-K. FLOOR HAS BUCKLED A LITTLE IN FRONT OF FUME HOODS. TILES MAY HAVE ASBESTOS ON THEM. □ REQ.PHYLLIS@5-2364 RITB034312	Planned Work	Progressing	BU0097-000	HAMELIN
8/13/2009	09-027722-000	CONTE, 162, FUME HOOD AIR FLOW TOO HIGH(139FPM) □ PLEASE ADJUST AIR FLOW. THANKS, □ REQ.YUNG MORGAN, Phone: 545-5118 iNET	Routine Service Call	Closed	BU0614-100	HUSTED
8/17/2009	09-028348-000	HASBROUCK LABORATORY ROOM 314 FUME HOOD NOT WORKING PHONED IN JIMMYWARREN □ REQ.LAURIE GOLDNER WEEKEND LOG SHEET 8/15/09	Dispatch Service Call	Closed	BU0124-100	LEE
8/17/2009	09-028399-000	MORRILL 4 NORTH, 417N, FUME HOOD BLOWER NOT WORKING. MOTOR & FAN MAY BE DAMAGED. □ REQ:PETER DAWSON@5-5936 iNET	Routine Service Call	Ready	BU0347-100	TOWNSEND
8/19/2009	09-029075-000	LEDERLE GRADUATE CENTER A - RM 1512, DOOR ON FUMEHOOD WILL NOT CLOSE FULLY. PLEASE CHECK AND REPAIR AS NEEDED. □ REQ:KEFAR JAHAN@50373 RITB034869	Routine Service Call	Closed	FH04121515	TOWNSEND
8/21/2009	09-029197-000	MARCUS HALL, ROOM #7 (LAMMDA LAB COMPLEX), ** Custodial Support ** ECE DEPT REQUEST FOR MEETING, DESIGN REVIEW, & COST ESTIMATE, TO "RE-FURBISH" LAB SPACE, TO INCLUDE THE FOLLOWING: □ REMOVAL OF SMALL SINK IN NORTHEAST ROOM, CAP PIPING, AND REPAIR WALL, REMOVE FUME HOOD AT ENTRANCE OF ROOM #7. (NORTHWEST CORNER), CAP DUCT, PLUMBING, ECT, AND REPAIR WALL, REMOVE (1) FUME HOOD, (1) SMALL SINK, IN (SOUTHWEST CORNER, CAP DUCT, PLUMBING, ECT, AND REPAIR WALL, REMOVE (1) LARGE STAINLESS STEEL SINK & REPLACE WITH (1) SMALL SINK, AS SELECTED BY PROFESSOR JACKSON, "UP-DATE" AC SYSTEM, AND REMOVE EXISTING AC SYSTEM, (NOTE: UTILIZATION OF EXISTING CHILLED WATER LINES SHOULD BE CONSIDERED), REMOVE CEILING RAIL & PAINT CEILING, REMOVE LARGE STEEL DOORS & REPLACE WITH CONVENTIONAL DOUBLE DOORS, PAINT ALL WALLS, THIS PROJECT MAY INVOLVE MOVING SOME TABLES, FURNISHINGS, (TO BE IDENTIFIED), OUT, DURING PROJECT. THANK-YOU... □ MADELENE ETKIN, ECE DEPT, IS REQUESTOR FOR THIS REVIEW & ESTIMATE, AT 5-4569, FAX 5-4611	Planned Work	Closed	BU0343-000	HAMELIN

Fume Hood Report

as of 10/07/09

8/24/2009	09-029936-000	ELAB II, 208, AT THE NORTH END OF LAB 208 THERE IS A SMALL WATER LEAK. WATER IS DRIPPING FROM THE INCOMING TEMPERED WATER LINE DIRECTLY ABOVE FUME HOOD #FH0657-208. (TO THE RIGHT AS YOU ENTER THE MAIN DOOR INTO THE LAB). IF YOU CAN NOT FIND THE PROBLEM EITHER ASK ONE OF THE STUDENTS IN THIS LAB OR ME. □ THANKS, □ SHERRIE W-Y □ ELAB II, 210B □ REQ.SHERRIE WEBB-YAGODZINSKI, Phone: 577-3231 iNET	Routine Service Call	Closed	BU0657-300	LEE
8/27/2009	09-030327-000	GRC , 16TH FLOOR INSTALL SURGE PROTECTION FOR COMPUTER BOARDS FOR FUME HOOD FANS. REQ. RAY SAMSON @ 5-6416	Routine Service Call	Closed	BU0412-200	HAMELIN
9/4/2009	09-021221-001	MORRILL 2, 418, FH0127-15 FUME HOOD MAKING LOUD NOISE AND HAD TO BE TURNED OFF. PLEASE CHECK AND REPAIR AS NEEDED.	Routine Service Call	Closed	BU0127-110	SAMSON
9/17/2009	09-032966-000	MORRILL 4N, 410, ONE OF THE LIGHTS IN THE FUME HOOD IS VERY DIM AND BURNING OUT, PLEASE REPLACE. □ REQ:JOY WARD@545-9469 iNET	Routine Service Call	Progressing	BU0347-200	TOWNSEND
9/30/2009	09-034628-000	MORRILL SCIENCE CENTER 4 - RM S364, AIR FLOW FOR THIS FUMEHOOD IS TOO HIGH. R-608@10:20 □ REQ:S.IVES@60449 RITB036028	Dispatch Service Call	Ready	FH0347-33S	TOWNSEND